

C9100-12 Typical EM-Gain

Sensitivity	EM-Gain
0	4
10	5
20	7
30	9
40	12
50	17
60	25
70	32
80	43
90	54
100	67
110	84
120	106
130	134
140	171
150	216
160	272
170	339
180	414
190	514
200	640
210	802
220	1025
230	1280
240	1535
250	1828
255	2000

